

VIEW FROM MANWAY INTO TANK AFTER CLEANING COMPLETED
SUSPENDED SCAFFOLDING SYSTEM STILL IN PLACE



LEFT SIDE JUST BELOW SPRING LINE IN DIRECTION OF MANWAY
AFTER TO CLEANING – SURFACE WET FROM WATER WASHING



AT THE SPRING LINE RIGHT SIDE OF TANK 1 AFTER CLEANING

